

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
CAL  
37-CORO,  
1-

Addendum to:  
HOTEL DEL CORONADO  
1500 Orange Avenue  
Coronado  
San Diego County  
California

HABS No. CA-1958

Photographs CA-1958-1 to CA-1958-22 were previously transmitted to the Library of Congress. This is Index to Photographs page 1.

Photographs by Perry E. Borchers of the Ohio State University, 1971.

- CA-1958-23      SE (ENTRANCE) FACADE, RIGHT EAST PORTION --INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1401L.
- CA-1958-24      CENTER OF SE (ENTRANCE) FACADE--LEVEL  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1402L.
- CA-1958-25      CENTER OF SE FACADE--INCLINED, CONVERGING  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1403LC.
- CA-1958-26      LEFT (SOUTH) PORTION OF SE FACADE--INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1404L.
- CA-1958-27      LEFT (SOUTH) PORTION OF SE FACADE--INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1404R.
- CA-1958-28      RIGHT (SOUTH) PORTION OF SE FACADE FROM BEACH--INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1405L.
- CA-1958-29      LEFT (WEST) PORTION OF SE FACADE FROM BEACH--LEVEL  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1406L.
- CA-1958-30      RIGHT (WEST) PORTION OF NW FACADE--LEVEL  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1407L.

**HOTEL DEL CORONADO**  
**HABS No. CA-1958**  
**Index to Photographs**  
**(Page 2)**

- CA-1958-31      LEFT (NORTH) PORTION OF NW FACADE--LEVEL  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1408L.
- CA-1958-32      RIGHT (NORTH) PORTION OF NE FACADE--INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1409L.
- CA-1958-33      CENTER OF NE FACADE, DISTANT VIEW--INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1410L.
- CA-1958-34      CENTER OF NE FACADE, CLOSE VIEW--INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1411L.
- CA-1958-35      LEFT (EAST) PORTION OF NE FACADE, EASTWARD PROJECTION--INCLINED  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1412L.
- CA-1958-36      RIGHT (EAST) PORTION OF SE FACADE, EASTWARD PROJECTION--LEVEL  
                 Copy photograph of photogrammetric plate  
                 LC-HABS-GS05-B-1971-1413L.